



# Your Inspection Report

**Vehicle Description:**

Inspection Date **9/28/2005**

<b>Full VIN:</b> 1GKFK66U21J265696	<b>Year:</b> 2002	<b>Engine Cylinders:</b> V8 OHV 16V
<b>Mileage:</b> 57215	<b>Make:</b> GMC	<b>Engine Lifters:</b> 6.0L
<b>Transmission Type:</b> Automatic	<b>Model:</b> Yukon Denali XL	<b>Engine Type:</b> Gas

Inspection Area:	Overall Rating:
<b>Body</b>	<b>Excellent</b>
<b>Glass</b>	<b>Excellent</b>
<b>Wipers</b>	<b>Excellent</b>
<b>Tires &amp; Wheels</b>	<b>Excellent</b>
<b>Interior Items</b>	<b>Excellent</b>
<b>Gauges</b>	<b>Excellent</b>
<b>Audio System</b>	<b>Excellent</b>
<b>Carpet &amp; Upholstery</b>	<b>Good</b>
<b>Trunk</b>	<b>Excellent</b>
<b>Electrical System</b>	<b>Excellent</b>
<b>Under Hood</b>	<b>Excellent</b>
<b>Road Test</b>	<b>Excellent</b>
<b>Additional Inspection Points</b>	<b>Good</b>



**EXTERIOR**

**BODY**

**OVERALL RATING: EXCELLENT**

Details:

<b>Front</b>	<b>OK</b>	<b>Right front</b>	<b>OK</b>
<b>Right doors</b>	<b>OK</b>	<b>Right rear</b>	<b>OK</b>
<b>Rear</b>	<b>OK</b>	<b>Left rear</b>	<b>OK</b>
<b>Left doors</b>	<b>OK</b>	<b>Left front</b>	<b>OK</b>
<b>Hood</b>	<b>OK</b>	<b>Roof</b>	<b>OK</b>
<b>Bumpers</b>	<b>Chip 0-1"</b>	<b>Trim</b>	<b>OK</b>
<b>Overall Condition of Paint</b>	<b>Good</b>		

**GLASS**OVERALL RATING: **EXCELLENT**

Details:

Windshield	OK	Right front window	OK
Right rear window	OK	Rear window	OK
Left rear window	OK	Left front window	OK

**WIPERS**OVERALL RATING: **EXCELLENT**

Details:

Front wipers	OK	Rear wipers	OK
Front wiper blades	OK	Rear wiper blades	OK
Front windshield washer	OK	Rear windshield washer	OK

**Comments on Exterior:**

The condition is excellent. There has been no body work or repainting done on the vehicle. There were minor pebble chips in the front bumper that were almost not visible. Other than that the paint and body are in excellent condition

**TIRES AND WHEELS**OVERALL RATING: **EXCELLENT**

Details:

Condition of tires	Good	Condition of wheels	Excellent
--------------------	------	---------------------	-----------

**Comments on Tires and Wheels:**

The alloy wheels are in great condition. The tires have about 70-80% tread on them.

**INTERIOR****TRUNK**OVERALL RATING: **EXCELLENT**

Details:

Spare tire	OK	Carpeting	OK
Tools	OK	Jack	OK
Floor pan	OK		

**ELECTRICAL SYSTEM**OVERALL RATING: **EXCELLENT**

Details:

Headlights	OK	Turn signals	OK
Taillights	OK	Electric windows	OK
Brake lights	OK	Electric seats	OK
Parking lights	OK		

**Comments on Electrical System:****UNDER HOOD****OVERALL RATING: EXCELLENT**

Details:

Oil leaks	NO	Exhaust leaks	NO
Exhaust smoke	NO		

**INTERIOR ITEMS****OVERALL RATING: EXCELLENT**

Details:

Glove box	OK	Head rests	OK
A/C cooling performance	OK	Door panels	OK
Heater operation	OK	Dash pad	OK
Hood release	OK	Vanity mirrors	OK
Cigarette lighter	OK		

**GAUGES****OVERALL RATING: EXCELLENT**

Details:

Speedometer	OK	Oil pressure	OK
Tachometer	OK	Amp meter	OK
Temperature	OK		

**AUDIO SYSTEM****OVERALL RATING: EXCELLENT**

Details:

Radio	OK	Tape player	OK
CD player	OK		

**CARPET AND UPHOLSTERY****OVERALL RATING: GOOD**

Details:

Front seats	OK	Rear seats	OK
Headliner	OK	Front carpeting	Stain 1-3"
Rear carpeting	Stain 1-3"		

**Comments on Interior:**

The interior has been well maintained. This SUV was not smoked in. There are no tears or rips or cracks in the leather seats or headrest. There is minor stains on the front and rear carpets.

**ROAD TEST****ROAD TEST****OVERALL RATING: EXCELLENT**

## Details:

Brake system - noise, vibration, effort	OK	Steering effort - drifting right or left	OK
Suspension - performance, noise, rough road test	OK	Transmission shift quality, smoothness, effort, slippage	OK
Idle	OK	Engine operating temperature	OK
Engine noise	OK	Transmission/Transaxle noise	OK
Acceleration	OK	CV joint/Drive axle noise	OK
Horn	OK	Parking brake operation	OK
Wind noise	OK	Engine performance	OK
Starting	OK		

**Comments on Road Test:**

The SUV started, idled and drove without any problems. It drove smoothly as well. Overall in excellent condition.

**ADDITIONAL INSPECTION POINTS****OVERALL RATING: GOOD**

## Details:

Sunroof	OK	Door locks	OK
Door handles	OK	Keyless entry	OK
Gas door	OK	Gas cap	OK
Roof rack	OK	Grille	OK
Fog lamps	OK	Evidence of smoke odor	OK
Tailgate/Liftgate	OK		

**Comments on Additional Inspection Points:**

REPORT COMES WITH ADDITIONAL PICTURES

[Print Report](#) | [Close Window](#)